

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N	< <have< th=""><th>County: Multnomah</th><th>Agency: MULTN</th><th>OMAH COUNTY</th></have<>	County: Multnomah	Agency: MULTN	OMAH COUNTY
1	7.5					minimums	ENTRY	POINT	
2	7.5			On our carrier and a second		been met for			
3	7.5					this day?	EP-	A	
4	7.6						PWS ID 41	01267	
5	7.6					N	MANNA HOUSI	E CHURC	H
6	7.7								
7	7.7					Sample no	riod: 41	2022	
8	7.8					Sample pe	eriod: <u>Aprill</u>	nth/Year	
9	7.7						,,,,	linii i oui	
10	7.7					Number of ex	cursions duri	ng this m	onth:
11	2.6					(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the			
12	7.6								
13	7.5								
14	7.6						parameter(s) fai	I below th	e minimum
15	7.6					set by the Sta	te.		
16	7.6								
17	7. 7					⊢Refere	nce ———	-	
18	7. 2								
19	7.6						/linimum Wate	_	
20	7.6					F	Parameter(s) as	s set by S	tate:
21	7.5					O A A A A A A A A A A A A A A A A A A A	pH 7.2		8 9 9 8 8 8 8 8
22	7.5						<u> </u>		
23	7.6	<u> </u>							
24	2.6					a de la companya de l			
25	7.2		<u> </u>						
26	7.7			<u> </u>					
27	7.6				-	Print Na	ame: <u>//2//29</u>	Thomas -	
28	2.6				1	Signatu	ire:		
29	7.6				-	Date &	Phone#: <u>5/s/</u> -	2002 50	3-382-199
30	7.6						DWP within 10		r end of
31						samplin			

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/