

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Other	YIN	a al lava	Our to Million of American		
1	7.6		**************************************			< <have minimums<="" td=""><td>County: Multnomah Agency: MULTN</td><td>OMAH COUNTY</td></have>	County: Multnomah Agency: MULTN	OMAH COUNTY	
2	7.6					been met for	ENTRY POINT		
3	7.0					this day?	EP-A		
4	7.5						PWS ID 4101267		
5	7.4					IM.	A		
6	7.8	•							
7	9					Sample pe	 		
8	7.9					oampie pe			
9	7,6								
10	7.6					Number of excursions during this month:			
11	7/5		- -						
12 13	7.3						d Distribution excursions	ns are ay in which the	
14	7.5					cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.			
15	7.7								
16	7.9								
17	217	•				⊢ <i>Referen</i>	nco		
18	7.9					Keleleli		İ	
19	7.4					M	inimum Water Quality		
20	7.6					Parameter(s) as set by State:			
21	7,7						pH 7.2		
	23								
	7.8								
24 25	7.2								
26	7.5								
	7.5					Drint Mar	ma: Elas Herrera		
28	7.4					Print Name: <u>Flay Hervera</u> Signature: <u>Flay America</u>			
29	5.5					_	hone#: \\ /6/ 202 4		
30	7.7						OWP within 10 days after	end of	
31	7.6					sampling			
10 = N	= Exc	ursion)	Total	N's	0	2	-		
				la.	ALVANOR STREET				

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/