

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1					
2					
3					
4					
5					
6	7.5				Y
7					
8					
9					
10					
11					
12					
13	7.3				Y
14					
15					
16					
17					
18					
19					
20	7.2				Y
21					
22					
23					
24					
25					
26					
27					
28	7.2				Y
29					
30					
31					
1 = ok	<b>1</b> = Exc	cursion	) Tota	l N's	

County: Marion Agency: MARION COUNTY						
ENTRY POINT						
EP-A						
PWS ID 4101464						
Hidden Meadows Water Assoc						
riod:February 2022						
Month/Year						

Number of excursions during this month: \_\_0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference					
Minimum Water Quality Parameter(s) as set by State:					
pH 7.2					

Print Name: Matt	Olson					
Signature:	Medt Elser	_				
Date & Phone#:_	3-1-2022	503-438-0471				
Send to DWP within 10 days after end of sampling period						

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/