

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рΗ	Alk	Phos	Other	Y/N	< <have< th=""><th>County: Marion Agency: MARION COUNTY</th></have<>	County: Marion Agency: MARION COUNTY	
1						minimums	ENTRY POINT	
2						been met for		
3						this day?	EP-A	
4							PWS ID 4101464	
5						Hidden Meadows Water Assoc		
6	7.4				Y	11100	uch Meadows Water Assoc	
7						Sample pe	ariod: June 2022	
8						Sample pe	Month/Year	
9								
10						Number of ex	cursions during this month: $_0$	
11						(Over 9 excur	sions in 6 months is a violation.	
12						•	d Distribution excursions are	
13	7.4				Y	-	An 'excursion' is any day in which the	
14						water quality parameter(s) fall below the minimum		
15						set by the Sta	te.	
16								
17						Reference		
18								
19						N	linimum Water Quality	
20	7.4				Y	Parameter(s) as set by State:		
21							pH 7.2	
22								
23								
24								
25								
26								
27						Print Na	ime: Matt Olson	
28	7.4				Y		re:	
29						Date & I	Phone#: 7-7-2022 503-438-0471	
30								
31						send to	DWP within 10 days after end of	
No = N	N = Ex	cursior	ד) Tota	l N's		Sampini	y period	

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/