

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	Sample Location (Other than Entry Point)	рН	Alk	PO4	other	Y/N
5		7.4				Y
12		7.0				Y
19		7.1				Y
26		7.1				Y
	(N = No = Excursion)			tal N's		0

<Has sample
met the
minimums?

ENTRY POINT - B
(Snider)</pre>

PWS ID: 41 0 1 5 1 8

System Name: Chehalem Springs

Sample Period: April 2024

Number of excursions during this Sample Period = \_\_\_\_0\_\_

(Number of locations when any WQP was less than the minimum.)

Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.

For OHA use only							
Minimum Water Quality							
Parameters as set by							
	1						
/.0							
	(Alkalinity)						
	(Orthophosphate)						
	()						
	•						
1	um Wa						

**Print Name: JJ Olson** 

Date: 05/09/2024

Send to Drinking Water Program within 10 days after end of sampling period: OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/