

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	Sample Location (Other than Entry Point)	рН	Alk	PO4	other	Y/N	<has sample<="" th=""></has>	
2		7.24				Y	<b>ENTRY POINT - B</b>	
8		7.34				Y		
15		7.33				Y	(Snider)	
22		7.32				Y	PWS ID: 41 0 1 5 1 8	
28		7.35				Y	System Name: Chehalem Springs	
	(N = No = Excur	sion)	То	otal N's	S	0	Sample Period: <u>February 2025</u>	

Number of excursions during this Sample Period = \_\_\_\_0\_\_\_\_

(Number of locations when any WQP was less than the minimum.)

Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.

Water Quality s as set by
(Alkalinity)
(Orthophosphate)
()
I <b>J Olson</b> Deffrey Olson

Send to Drinking Water Program within 10 days after end of sampling period: OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/