

## Water Quality Parameter Monitoring Form

# Lead & Copper Rule Corrosion Control

Day	Sample Location (Other than Entry Point)	pH	Alk	PO4	other	Y/N
1						
2						
3						
4						
5						
6						
7		7.44				Y
8						
9						
10						
11						
12						
13						
14		7.46				Y
15						
16						
17						
18						
19						
20						
21		7.37				Y
22						
23						
24						
25						
26						
27						
28		7.38				Y
29						
30						
31						
(N = No = Excursion) <b>Total N's</b>						0

<Has sample met the minimums?

**ENTRY POINT - B (Snider)**

PWS ID: 41 0 1 5 1 8

System Name: Chehalem Springs

Sample Period: NOV 2025

Number of excursions during this Sample Period = 0

*(Number of locations when any WQP was less than the minimum.)*

*Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.*

*For OHA use only*

**Minimum Water Quality Parameters as set by**

pH	7.0	
Alk		<i>(Alkalinity)</i>
PO4		<i>(Orthophosphate)</i>
Other		<i>(_____)</i>

Print Name: Curtis Olson

Signature: *Curtis Olson*

Date: 12/05/2025

Send to Drinking Water Program within 10 days after end of sampling period:  
 OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350  
 Phone (971) 673-0405 Website: <http://healthoregon.org/dwp/>