

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Clackamas Agency: Clack</th></have<>	County: Clackamas Agency: Clack	
2/6	7.8				4	minimums	ENTRY POINT	
2/15	7.7				0	been met for		
2/18	7.4			- 10	8	this day?	EP-A	
3/27	7.4				y		PWS ID 4105086	
					0	POLEHN HEIGHTS WATER ASSN.		
						-		
2/-01		20			-	Sample period: FEBRYARY 2022		
2/28		30					Month/Year	
						Number of excursions during this month: (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.		
	-							
			-					
				·		oraro.	•	
						Rafa	rence	
						7,676	rende	
							Minimum Water Quality	
							Parameter(s) as set by State:	
							pH 7.2	
				V				
				100				
							\$1 ./ ///	
						Print Name: Sheila H. Wahl Signature: Sheila H. Wahl		
						Date:		
No = N = Excursion) Total N's					Ø	Send to DWP within 10 days after end of sampling period		
	DHS Drinking Water Program PO Box 14350 Portland OR 97293-0350							

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: wwww.ohd.hr.state.or.us/dwp