

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

	of	of human services						
Day	рН	Alk	Phos	Sili	Y/N	< <have< td=""><td>County: Clackamas Agency: Clack</td></have<>	County: Clackamas Agency: Clack	
6/3	7.8				4	minimums been met for	ENTRY POINT	
4/6	7,6				ly	this day?	EP-A	
6/12	7.8				y		PWS ID 4105086	
6/15	7,6				y	POLEHN HEIGHTS WATER ASSN.		
6/21	7,5		-		dy	·	LEIN HEIGHIS WILLENING	
1/24	7.6	-			y		T 2233	
						Sample period: <u>June 2022</u> Month/Year		
						Number of excursions during this month:  (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative).  An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the		
				-				
					-			
				1	-			
				-	+-	State.		
	-							
	+		1			Ref	Reference	
							Minimum Water Quality	
	-						Parameter(s) as set by State:	
			_			1	pH 7.2	
		_			+	-		
	+-			-		-		
	+				+			
	+	+	_	+-	+			
	1	+-		+			Ci (/ 1/10) //	
	+					Print Name: Sheila H. Wahl Signature: Sheila H. Wahl		
Signature: Sheila H								
						Date:	10 July 2022	
(No = N = Excursion) <b>Total N's</b>						Send to I	Send to DWP within 10 days after end of	
			2000			sampling	period O Box 14350, Portland, OR 97293-0350	

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: wwww.ohd.hr.state.or.us/dwp