

Water Quality Parameter Monitoring Form

## Lead & Copper Rule Corrosion Control

Day	рΗ	Alk	Phos	Other Y	<b>//N</b>	< <have< th=""><th>County: Clackamas Agency: CLACKAMAS COUNTY</th></have<>	County: Clackamas Agency: CLACKAMAS COUNTY	
1	7.5				Ч	minimums	ENTRY POINT	
2						been met for		
3						this day?	EP-A	
4	7.4				4		PWS ID 4105086	
5		25			4	P0	DLEHN HEIGHTS WATER ASSN	
6						E E		
7	7.4	-			4	Sample	pariod: Tulu 2023	
8						Sample	e period: July 2033 Month/Year	
9							montan roar	
10		—				Number of	excursions during this month:	
11	7.4				4	(Over 9 ex	cursions in 6 months is a violation. Entry	
12							Distribution excursions are cumulative).	
13	7.6				Ч	An 'excursion' is any day in which the water quality		
14							s) fall below the minimum set by the	
15	_					State.	11 :	
16	7,3				4	Well	#1	
17		25			4	Ref	erence	
18								
19	7.4				4		Minimum Water Quality	
20							Parameter(s) as set by State:	
21			_				pH 7.2	
22	7.4				4		Alk 25.0 (Alkalinity)	
23								
24								
25								
26								
27						Print	Name: Sheila H. Wahl	
28	6.8	1			N	Sign	Name: <u>Sheila</u> H. Wahl ature: <u>Sheila</u> H. Wahl	
29						Date	& Phone#: <u>8/7/23 911-998-6481</u>	
30	7.5				4	Cond	to DWP within 10 days after end of	
31							ling period	
(No = 1	No = N = Excursion) Total N's /							

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/