

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1					
2					
3					
4	7,6	25			iA
5					8
6					
7	:7.2				iΛ
8					7
9					
10	7.4	25			y
11					8
12					
13	7,6				И
14					7
15					V
16	7.4	25			4
17					9
18					
19	7.5				И
20					1
21					
22	7.6	30			и
23					1
24					
25	7.4				is
26					0
27					
28					
29					
30	7.5	30			U_
31					
lo = N	= Exc	ursion)	Total	N's	d

<<Have
minimums
been met for
this day?</pre>

County: Clackamas Agency: CLACKAMAS COUNTY

ENTRY POINT

EP-A

PWS ID 4105086

POLEHN HEIGHTS WATER ASSN

Well #2

Sample period: <u>December</u>

ecember 2023

Month/Year

Number of excursions during this month: ____

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

		ater Quality) as set by State
рН	7.2]
Alk	25.0	(Alkalinity)
](·)

Print Name: Sheila H. Wah!
Signature: Annie H. Wah!
Date & Phone#: 10 Jan 2034 971-998-648!

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/