

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

рН	- The same of the		L	Y/N
7,4	30		3,100	1
				9
7.6				4
				y
7.6	25			9
				0
7,4		200,000		7
				0
7.4	25			4
				y
7.6				11
				8
7.5	30			y
				0
	t.			
7.6	30			4
				0
			PHO5568411	
	1	V 5		
	7.4	7.6 25 7.7 25 7.6 7.6 7.6 7.6 7.6 7.6 7.6 7.6 7.6 7.6	7.6 25 7.6 7.6 7.6 7.6 7.6 7.6 7.6 7.6 7.6 7.6	7.6 25 7.6 7.6 7.5 30

<<Have
minimums
been met for
this day?</pre>

County: Clackamas Agency: CLACKAMAS COUNTY

## **ENTRY POINT**

EP-A

PWS ID 4105086

POLEHN HEIGHTS WATER ASSN

Sample period: APRIL 2034

Month/Year

Number of excursions during this month: \_\_\_\_\_\_\_

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

	um Water Quality eter(s) as set by Sta
pH Alk	7.2 25.0 (Alkalinity)
N	Sha'/a W. /

Print Name: Sheila H. Wahl
Signature: Aheila H. Wahl
Date & Phone#: MAYA, 2024 971-998-6481

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/