

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

	Day	рН	Alk	Phos	Other	Y/N
	1					
	2	7.4				iA
	3					9
	4					
	5	7,2	25			и
	6					8
	7					
	8	7,2				Ц
	9					0
	10					
	11					
	12	7,3				y
	13					0
	14	7.4	25			y
	15					0
-	16					
		7.3				9
	18					0
	19					
-		7.3				4
-	21					7
-	22					
-	23	7.5	25			y
-	24					
-	25					_
-		7.2				9
-	27					0
-	28					_
+	29	7.4				4
-	30					0
	31					
(1/	0 = N	= Excl	ursion)	Total	N's	1

<<Have
minimums
been met for
this day?</pre>

County: Clackamas Agency: CLACKAMAS COUNTY

ENTRY POINT

EP-A

PWS ID 4105086

POLEHN HEIGHTS WATER ASSN

Well#1

Sample period: October 2034

Month/Year

Number of excursions during this month: \_\_\_\_\_\_\_

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

		ater Quality ) as set by State
рН	7.2	7
Alk	25.0	(Alkalinity)

Print Name: Sheila H. Wahl
Signature: Sheila H. Wahl
Date & Phone#: 11-2-24 503-631-3036

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/