

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1		30			1A
2					y
3	7.7				iA
4					9
5					
6	7,7	25			И
7					y
8					
9	7.7	30			i)
10					y
11					
12	7.7				u
13					y
14					
15	7.5	30			U
16					y
17					
18	7.7	30			И
19					4
20					
21	7.7	25			14
22					4
23					
	7,4				ч
25					1
26					
27	7.8	30			4
28					1
29					
	7.7				1
31				0	F
lo = N	= Exc	ursion)	Total	N's	0

<<Have
minimums
been met for
this day?</pre>

County: Clackamas Agency: CLACKAMAS COUNTY

ENTRY POINT

EP-A

PWS ID 4105086
POLEHN HEIGHTS WATER ASSN

Sample period: January 2035

Well #2

MonthlyYear

Number of excursions during this month: _O

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

	set by State:
pH 7.2	
Alk 25.0 (Alk	ralinity)

Print Name: <u>Sheila N. Wahl</u>

Signature: <u>Sheila H. wahl</u>

Date & Phone#: <u>2/10/25 971-998-6481</u>

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/