

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	Sample Location (Other than Entry Point)	рН	Alk	PO4	other	Y/N
7		7.28				Y
21		7.26				Y
/N = No = Everymien > Trital NU						

(N = No = Excursion) Total N's <Has sample met the minimums?

**ENTRY POINT A** 

PWS ID: 41 | 0

System Name: Oxberg Water

Sample Period: Every 2 weeks -

**April 2025** 

Number of excursions during this Sample Period = 0

(Number of locations when any WQP was less than the minimum.)

Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.

For OHA use only						
Minimum Water Quality Parameters as set by						
pH 7.	2					
Alk	(Alkalinity)					
PO4	(Orthophosphate)					
Other	()					

**Print Name: Curtis Olson** 

Signature: Curtis Olson

Date: <u>05/05/2025</u>

Send to Drinking Water Program within 10 days after end of sampling period: OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/