

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

у	Sample Location (Other than Entry Point)	рН	Alk	PO4	other	Y/N	<has sample<="" th=""></has>		
		7.21				Y	met the ENTRY POINT A minimums?		
		7.80				Y			
						0	PWS ID: 41 0 5 3 0 8		
	(N = No = Excursion) Total N's			0	System Name: <u>Oxberg Water</u>				
							Sample Period: <u>Every 2 weeks – Ma</u>		
							<u>2025</u>		
							Number of excursions during this		
						Sample Period = <u>0</u>			
							(Number of locations when any WQP		
							was less than the minimum.)		
							Note: Entry Point and Distribution		
							Excursions are cumulative. Add Entry		
							Point and Distribution Excursions to ge		
							total for sample period.		
							For OHA use only		
							I OF OF A use only		
							Minimum Water Quality		
							Parameters as set by		
							pH 7.2		
							Alk (Alkalinity)		
							PO4 (Orthophosphate)		
							Other (Other)		
							Drint Names Curtis Olaan		
							Print Name: <u>Curtis Olson</u> Signature: <u>Curtis Olson</u>		

Send to Drinking Water Program within 10 days after end of sampling period: OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/