



Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Y/N
1	7.53			
2	7.52			
3	7.55	63.0	1.43	
4	7.59			
5	7.54			
6	7.54			
7	7.49			
8	7.70			
9	7.72			
10	7.58	59.0	1.56	
11	7.61			
12	7.54			
13	7.56			
14	7.52			
15	7.60			
16	7.80			
17	7.73	58.0	1.41	
18	7.35			
19	7.39			
20	7.70			
21	7.50			
22	7.48			
23	7.43			
24	7.69	56.0	0.75	
25	7.50			
26	7.29			
27	7.31			
28	7.52			
29	7.52			
30	7.50			
31	7.52			

(No = N = excursion) **TOTAL N'S** 0

<<Have minimums been met for this day?

County: Clatsop Agency: CLATSOP COUNTY

ENTRY POINT
EP-A

PWS ID 4190416
Georgia-Pacific CLCP Wauna

Sample Period: May / 2021
Month/Year

Number of excursions* during this month: 0 (Count the number of days when any WQP was less than the minimum required)

Total excursions during the previous 5 months: 0 (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

For OHA use only

Minimum Water Quality Parameters as set by

pH	7.2	
PO4	0.5	(Orthophosphate)

Print Name: Terry Force Signature:

Date: 6-1-21 Phone: 503-455-3331

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: <http://healthoregon.org/dwp/>

0