



Water Quality Parameter Monitoring Form

**Lead & Copper Rule Corrosion Control**

Day	pH	Alk	Phos	Y/N
1	7.48			
2	7.56			
3	7.46			
4	7.47			
5	7.59			
6	7.69			
7	7.48	52.0	1.5	
8	7.60			
9	7.66			
10	7.58			
11	7.64			
12	7.63			
13	7.68			
14	7.57	54.0	1.3	
15	7.54			
16	7.70			
17	7.69			
18	7.55			
19	7.36			
20	7.48			
21	7.70	52	1.2	
22	7.65			
23	7.53			
24	7.57			
25	7.75			
26	7.80			
27	7.70			
28	7.67	52		1.2
29	7.68			
30	7.69			
31				
(No = N = Excursion)				0
TOTAL N'S				

<<Have minimums been met for this day?

County: Clatsop Agency: CLATSOP COUNTY

**ENTRY POINT**  
**EP-A**

**PWS ID 4190416**  
**Georgia-Pacific CLCP Wauna**  
**Sample Period: JUNE/2021**  
Month/Year

Number of excursions\* during this month: 0 (Count the number of days when any WQP was less than the minimum required)


Total excursions during the previous 5 months: 0 (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative )

For OHA use only

**Minimum Water Quality Parameters as set by**

pH 7.2  
PO4 0.5 (Orthophosphate)

Print Name: Terry Force

Signature: 

Date: 7/7/2021

Phone: 503-455-3331

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: <http://healthoregon.org/dwp/>