



Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Y/N
1	7.6			Y
2	7.6			Y
3	7.6			Y
4	7.5	44.9	1.39	Y
5	7.5			Y
6	7.5			Y
7	7.7			Y
8	7.8			Y
9	7.4	51.4	1.09	Y
10	7.5	52.9	1.14	Y
11	7.5			Y
12	7.6			Y
13	7.7			Y
14	7.8			Y
15	7.7			Y
16	7.7	54.5	1.11	Y
17	7.9			Y
18	7.9			Y
19	7.8			Y
20	7.8			Y
21	7.8			Y
22	7.8			Y
23	7.8	57.5	1.14	Y
24	7.8			Y
25	7.8			Y
26	7.8			Y
27	7.9			Y
28	7.6			Y
29	7.7			Y
30	7.8			Y
31	7.8			Y
(No = N = Excursion)				
TOTAL N'S				0

<<Have minimums been met for this day? County: Clatsop Agency: CLATSOP COUNTY

ENTRY POINT
EP-A

PWS ID 4190416
Georgia-Pacific CLCP Wauna
Sample Period: MONTH / YEAR
Month/Year

Number of excursions* during this month: 0 (Count the number of days when any WQP was less than the minimum required)


Total excursions during the previous 5 months: 0 (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

For OHA use only

Minimum Water Quality Parameters as set by

pH 7.2
 PO4 0.5 (Orthophosphate)

Print Name: Terry Force

Signature: 

Date: 2/2/2023

Phone: 503-455-3331

Send to DWP within 10 days after end of sampling period
 OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: <http://healthoregon.org/dwp/>