

Water Quality Parameter Monitoring Form
Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Other	Y/N
1	7.4				
2	7.3				
3	7.4				
4	7.7	.89			
5	7.5				
6	7.4				
7	7.5				
8	7.3				
9	7.6				
10	7.4				
11	6.2				
12	7.7				
13	7.5				
14	8.0				
15	8.0				
16	7.4	.91			
17	7.5				
18	7.4				
19	7.6				
20	7.6				
21	7.6				
22	7.4				
23	7.6				
24	7.7				
25	7.5				
26	7.6				
27	7.5				
28	7.5	.78			
29	7.6				
30	7.4				
31					

<<Have

minimums
been met for
this day?

ENTRY POINT

PWS ID: 41 90531

System Name: Jewell SD #8

Entry Point: _____

Sample Period: 9/2025
Month/Year

Number of excursions* during this month: 0

(Count the number of days when any WQP was less than the minimum required)

Total excursions during the previous 5 months: _____

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

For OHA use only

**Minimum Water Quality
Parameters as set by**

pH 7.2
Alk = (Alkalinity)
PO4 (Orthophosphate)
Other ()

Print Name: RON Wanner

Signature: R. Wanner

Date: 10/3/25

Send to DWP within 10 days after end of sampling period

(No = N = Excursion) Total N's 0

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: <http://healthoregon.org/dwp/>