

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

- ·	Day	рН	Alk	Phos	Other	Y/N	- Haya	— т		
	1				₹	_	< <have minimum<="" td=""><td>I</td><td>County: Marion Agency: MARION COUNTY</td></have>	I	County: Marion Agency: MARION COUNTY	
	2	8.56		 	_		been me	I	ENTRY POINT	
	3	<i>p</i>	 	 			this day		EP-A	
	4		 					<u></u>	PWS ID 4190587	
	5		-				SILVER CREST SCHOOL			
	6						SIE VER CREST SCHOOL			
	7					_	Sample period: <u>November 2021</u> Month/Year			
	8									
	9									
	10						Number of excursions during this month: (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.			
	11									
	12									
	13				[
	14									
	15			_						
		8,67			_					
	17						⊢Reference —————			
	18									
	19							Minimum Water Quality		
	20							Parameter(s) as set by State:		
	21		_							
	22								P11	
	23									
	24									
	25									
	26									
	27						F	Print Name: HEIGH FOTJCAL		
	28					[Signature: 11/3/3/			
	29-	- 1 J.	-							
-		7046							DWP within 10 days after end of	
	31							ampling		
(V	10 = N	l = Exc	ursion)	Total	N's			. 0	•	

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/