

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

	Day	рН	Alk	Phos	Other	Y/N	< <have< th=""><th>County</th><th>r: Marion</th><th>Agency: MARION COUNTY</th></have<>	County	r: Marion	Agency: MARION COUNTY	
*	1						minimums	EN	TRY	POINT	
	2						been met fo			P-A	
	3						this day?				
	4	9,45	167				PWS ID 4190587 SILVER CREST SCHOOL				
	5		 .								
	6								^		
	7	:					Sample period: AND 2022 Month/Year Number of excursions during this month:				
	8										
7	9		·								
	10										
	11	00	1'76	 			(Over 9 excursions in 6 months is a violation.				
	12 13	9,9	176				Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.				
	14		-:-								
	15			<u> </u>							
•	16		<u> </u>	<u> </u>	<u> </u>		•				
	17						Reference				
	18	9.83	175								
	19	11.00	1 />					Minimum Water Quality			
	20	1					Parameter(s) as set by State:				
	21				1						
	22							pH	7.2		
	23										
	24										
	25										
	26						Print Name: Dystin Hoehre				
	27										
	28						Signature: 3/28/82				
	29	9.75	161								
	30						Send to DWP within 10 days after end of				
	31							npling period		to dayo altor ond or	
(No = N = Excursion) Total N's										

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/