

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

	Day	рН	Alk	Phos	Other	Y/N	< <have< th=""><th></th><th>County: Marion</th><th>Agency: MARION COUNTY</th></have<>		County: Marion	Agency: MARION COUNTY	
\$ [	1	8,74	103				minimun		ENTRY	POINT	
	2						been me		EP	- <b>A</b>	
	3						this day	(			
	4						PWS ID 4190587				
	5						SILVER CREST SCHOOL Sample period: <u>August 2022</u> Month/Year				
	6										
	7				ļ						
	8	7.92			ļ						
	9					ļ	Number of excursions during this month: (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are				
	10	<u> </u>									
ſ	11				ļ	<b> </b>					
	12	<u> </u>			<u> </u>	<b>  </b>					
	13	<u> </u>			<u> </u>		cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum				
	14	<b>_</b>	<u> </u>			<b> </b>	set by the State.				
	15	. 		-	<u> </u>						
*	16		1110								
	17	7,45	143				Reference				
	18	<u> </u>				-			ter Quality		
	19							Minimum Water Quality Parameter(s) as set by pH 7.2		r(s) as set by State:	
	20				+						
	21	31.70	100			-					
	22	1.17	158		_					à	
	23						  -				
	24	_			-			ļ			
<b>*</b>	25 26			-							
	20					-	ļ	Drink N	Inma: Dus	tin Hoehne	
	28					_	Print Name: Dussin Hoenne Signature:				
	29						1	-		Tax	
	30		150				1	Date & Phone#: 8///&			
	31				_		1		Send to DWP within 10 days after end of sampling period		
	L		Vourel		tal Nº		4	sampli	ng penou		
	(No =			on) <b>To</b> ʻ )rinkir			_ rogram. P	O Box	14350, Portlar	nd, OR 97293-0350	

Phone (971) 673-0405 Website: http://healthoregon.org/dwp/