

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

٠, [Day	рΗ	Alk	Phos	Other	Y/N	< <have< th=""><th></th><th>County: Marion Agency: MARION COUNTY</th></have<>		County: Marion Agency: MARION COUNTY		
*	1						minimums been met for this day?		ENTRY POINT		
	2	7.44	133						EP-A		
	3							<u> </u>			
	4						PWS ID 4190587				
	5						SILVER CREST SCHOOL				
*	6						Number of excursions during this month: (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.				
	7										
	8			<u> </u>	<u> </u>						
	9				<u>:</u>						
	11	8.01	129								
	12	7,01	10/	-	 						
	13										
	14			†							
	15										
	16										
*	17						Reference				
	18										
	19		ļ	ļ		<u> </u>	Minimum Water Quality Parameter(s) as set by State: pH 7.2				
	20										
		8,87	12]		 						
	22	<u> </u>	-				1	}			
	23	<u> </u>	 			-	Print Name: Dustin Hochne				
古	24	<u> </u>									
	25 26	 	-	-							
	27	<u> </u>	 		+	+-					
	28	75	3 /31	 		-	1				
	29	 ""			1	+	Signature:				
	30	1									
	31	1					sampling period				
	 (No =	N = E:	xcursio	on) To t	al N's	3		Junipi	a ba.		
	OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350										

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/