

10

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

	Day	рН	Alk	Phos	Other Y	/N	< <have< th=""><th></th><th>County: Marion</th><th>Agency: MARION COUNTY</th></have<>		County: Marion	Agency: MARION COUNTY	
	1	3 - 52 + 72 + 73 Mg 2003 - 2					minimun	i	ENTRY	POINT	
	2			mine signification (the control strength			been me	1	ם יתו	P-A	
	3						this day	<i>:</i>			
	4						PWS ID 4190587 SILVER CREST SCHOOL				
+	5	7.46	137								
•	6			mengenaman probabilis (1914)			Sample period: <u>January 2023</u>				
	7										
	8						Month/ ∀ ear				
	9					_					
4	-	7.49	148			\dashv	Number of excursions during this month: (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the				
	11					_					
	12										
	13						water quality parameter(s) fall below the minimum				
	14						set by the State.				
	15	·				_					
VX		7.64	155				Ç	Doford	0000		
	17	ASSET	(MAS)				Minimum Water Quality				
	18	WASE!	VOICE			7					
	20								as set by State:		
	21			\vdash					[7.0		
	22								pH 7.2		
L	23	7.58	139								
T	24	1					-				
	25										
	26										
	27							Print N	lame: <u>US</u>	Fin Heehne	
	28							Signature:			
	29						Date & Phone#: 1/5/22 503 873 5303				
4	30	30 7.70 162					Send to DWP within 10 days after end of				
U	31						sampling period				
	(No =	N = E	xcursio	n) To	tal N's			•			
					L		and				

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/