

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

	Day	рН	Alk	Phos	Other	Y/N	< <have< th=""><th>County: Marion Agency: MARION COUNTY</th></have<>	County: Marion Agency: MARION COUNTY		
	1						minimums	ENTRY POINT		
	2						been met for	EP-A		
	3						this day?			
	4							PWS ID 4190587		
*	5						SILVER CREST SCHOOL Sample period:			
	6									
	7	7.76	144							
	8									
	9			············	<u></u>					
	10									
	11	18 9	16				(Over 9 excursions in 6 months is a violation.			
	12	10:3	160				Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.			
	14									
	15									
>		10.3	166	<u> </u>			•			
	17						Pofe	erence —		
	18						Kere	er er ree		
*	19						Minimum Water Quality			
	20						Parameter(s) as set by State:			
	21							pH 7.2		
	22							pii		
	23							4		
	24									
	25				ļ					
	26	9,78	130							
	27			<u> </u>			Print Name: Dustin Hoehne			
	28		<u> </u>		ļ			ature:		
	29					<u></u>	Date	& Phone#: 503-873-5303		
	30						Send	to DWP within 10 days after end of		
	31			<u> </u>				ling period		
- ($N_0 = 1$	N = Ex	cursior	1) Tota	al N'e	1				

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/