

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

	Day	рН	Alk	Phos	Other	Y/N	< <have< th=""><th>County: Marion Agency: MARION COUNTY</th></have<>	County: Marion Agency: MARION COUNTY	
	1						minimums	ENTRY POINT	
	2						been met for		
	3						this day?	EP-A	
寒	4						Sample period: Sample period: Month/Year Number of excursions during this month: (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.		
	5	10.1	129						
	6								
	7								
	8								
A	9								
	10	10,2	175						
	11								
	12								
	13								
	14								
	15		<u> </u>						
+	16						Minimum Water Quality Parameter(s) as set by State:		
	17	10 7	100						
	18 19	10.2	101						
	20	and the second s							
	21						arameter(s) as set by State.		
*	22	Stocked Street S						pH 7.2	
	23							:	
	24								
	25	9.33	112						
	26	71-0							
	27						Print Name: Dustin Hoehns		
	28								
	29						Signature: 503-873-5303		
*	30							Y	
	31	9.53	125				Send to DWP within 10 days after end of		
(No = N = Excursion) Total N's sampling period									

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/