

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N	< <have< th=""><th>County: Marion Agency: MARION COUNTY</th></have<>	County: Marion Agency: MARION COUNTY
1						minimums	ENTRY POINT
2						been met for	EP-A
3	area					this day?	
4	7.47	102					PWS ID 4190587
5	· · ·					-	SILVER CREST SCHOOL
6							
7 8						Sample pe	eriod: <u>Decembere</u> 2024
9							Month/Year
<u></u>	·····					Bi I c	
10	7.96	120					cursions during this month:
12	1.46	16 /				(Over 9 excur	sions in 6 months is a violation.
13							nd Distribution excursions are
14						water quality i	An 'excursion' is any day in which the parameter(s) fall below the minimum
15	•					set by the Sta	
16							
17						⊢Refere	
1	8.54	122				Releie	nice —
19	<u> </u>						linimum Water Quality
₹ 20	9.32	177					Parameter(s) as set by State:
21							
22		****					pH 7.2
23							
24							
25							
26							
27						Print Na	ime: Jeff Anderman
28						Signatu	
29							Phone#: 1/1/2025 93-991-65
	1.90	128					7 1
31						sampling	DWP within 10 days after end of
	_	ursion)				Ownpling	, polica

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/