

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

	Day	рН	Alk	Phos	Other	Y/N	< <have< th=""><th>County: Marion Agency: MARION COUNTY</th></have<>	County: Marion Agency: MARION COUNTY		
]	1						minimums	ENTRY POINT		
	2						been met for	r		
	3						this day?	EP-A		
	4							PWS ID 4190587		
	5						SILVER CREST SCHOOL			
	6	- 3 - 53	· · · · · · · · · · · · · · · · · · ·				Sample period: MAVCM ZOZS Month/Year			
W	7	7,87	143							
ļ	8									
	9									
	10						Number of excursions during this month: (Over 9 excursions in 6 months is a violation.			
	11	021	177							
4	12	8.3/	141				Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.			
-	13 14									
-	15									
-	16									
	17									
	18				-		Ret	erence		
		B.S	116					Minimum Water Quality		
1	20	Dist	LTU					Parameter(s) as set by State:		
l	21						pH 7.2			
f	22			.,				pH 7.2		
ľ	23									
İ	24									
ľ	25									
	26						Print Name: Jeff Alderman			
¥	27	9.51	137							
Ì	28						Signature: Date & Phone#: 5			
	29									
	30						Send to DWP within 10 days after end of sampling period			
	31									
(N	lo = N	l = Exc	ursion	Total	l N's [Odiff	9 Politod		

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/