

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

) Day	рН	Alk	Phos	Other	Y/N	< <have< th=""><th>County: Lane Agency: LANE COUNTY</th></have<>	County: Lane Agency: LANE COUNTY
1				Temp	-	minimums	ENTRY POINT
2						been met for	EP-A
3	7.6			148	<u>د</u>	this day?	
4							PWS ID 4190894
5						APF	PLEGATE ELEMENTARY 66
6							
7						Sample pe	eriod: July 2025
8						Outilipio p	Month/Year
9							
10	7.6			14.9		Number of ex	cursions during this month: <u> </u>
11						(Over 9 excurs	sions in 6 months is a violation. Ent
12						Point and Dist	ribution excursions are cumulative)
13						An 'excursion'	is any day in which the water quali
14							fall below the minimum set by the
15						State.	
16							
17	7.7			14.8	۷_	Reference	
18						_	
19							Minimum Water Quality
20						۲	Parameter(s) as set by State:
21							pH 7.6
22							
23	7 -1			HA E	2		
24	7,7			14.6			
25 26							
27						8	72-
28							ime: Bryan Wood
29						Signatu	
30							Phone#: 08/6/25
-	7,7			14.8		Send to DWP within 10 days after end of	
31 						sampling	

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/