



# Water Quality Parameter Monitoring Form

## Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Other	Y/N
1	7.52				Y
2					
3					
4	7.53				Y
5					
6					
7	7.54				Y
8					
9					
10	7.50				Y
11					
12					
13					
14	7.51				Y
15					
16					
17					
18	7.41				Y
19					
20					
21	7.38				Y
22					
23	7.35				Y
24					
25					
26					
27					
28	7.30				Y
29					
30	7.29				Y
31					

<<Have minimums been met for this day? **ENTRY POINT**

PWS ID: 41 91211

System Name: Pacific High School

Entry Point: A

Sample Period: November  
Month/Year

Number of excursions\* during this month: 0  
 (Count the number of days when any WQP was less than the minimum required)

Total excursions during the previous 5 months: 0  
 (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

For OHA use only

**Minimum Water Quality Parameters as set by**

pH

Alk  (Alkalinity)

PO4  (Orthophosphate)

Other  ( )

Print Name: Don A Droscher

Signature: Don A. Droscher

Date: 12-1-22

Send to DWP within 10 days after end of sampling period

(No = N = Excursion) Total N's 0

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350  
 Phone (971) 673-0405 Website: <http://healthoregon.org/dwp/>