

Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Other	Y/N
1					
2	7.20		1.0		Y
3					
4					
5	7.05		1.0		Y
6					
7	7.04		1.0		Y
8					
9	7.11		1.0		Y
10					
11					
12	7.31		1.0		Y
13					
14	6.87		1.0		Y
15					
16					
17					
18					
19	7.36		1.0		Y
20					
21					
22	7.34		1.0		Y
23	7.23		1.0		Y
24					
25					
26					
27	7.29		1.0		Y
28	7.27		1.0		Y
29					
30	7.28				
31					

<<Have minimums been met for this day?

ENTRY POINT

PWS ID: 41

System Name: DIXIE ELEMENTARY SD 509J

Entry Point: EP-A

Sample Period: MAY

Month/Year

Number of excursions* during this month: 0

(Count the number of days when any WQP was less than the minimum required)

Total excursions during the previous 5 months:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

For OHA use only

Minimum Water Quality Parameters as set by STATE:

pH	<input type="text" value="6.7"/>	
Alk	<input type="text"/>	(Alkalinity)
PO4	<input type="text" value="1."/>	(Orthophosphate)
Other	<input type="text"/>	()

Print Name: Mike Buark

Signature: Michael Buark

Date: 5/30/25

Send to DWP within 10 days after end of sampling period

(No = N = Excursion) Total N's

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: <http://healthoregon.org/dwp/>