

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

of human services								
Day	рН	Alk	Phos	Sili	Y/N		County: Linn Agency: Linn	
7/1	7.6					minimums been met for	ENTRY POINT	
7/5	7.5					this day?	EP-A	
7/6	7.4						PWS ID 4191707	
7/1	4.6					PLEASANT VALLEY ELEM SD #55 Sample period: Suly 202 Month/Year		
7/a	7.3							
7/12	7.5							
7/13	7.6							
7/14	7.4							
<u>7/s</u>	7.5							
116	<u> </u>		ļ			Number of excursions during this month:		
7/19	₹ . 5							
7/21	7.5							
7/22	7.4		1					
7/26	7.6					State.		
7/27	7.5					T 11.2 SC C 2001		
7/28	7.5		<u> </u>		 	Reference Emailed 8-6-200		
							Minimum Water Quality	
							Parameter(s) as set by State:	
			ļ				pH 7.2	
	<u> </u>		ļ .		 			
		<u> </u>	<u> </u>			-		
				1	-	-		
				-	 			
						Print Name: Lon, Weinman		
			<u> </u>		ļ	Signature: Jon' M		
	<u></u>		_			-	5-6-2021	
10 = 1	N = Ex	cursio	n) Tot a	ıl N's		Send to DWP within 10 days after end of sampling period		
		.	10. 5	.:	. \//-		period PO Boy 14350 Bortland OD 07203.035	

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp