

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

of human services								
Day	рН	Alk	Phos	Sili	Y/N		County: Linn Agency: Linn	
12/2	7.4					minimums	ENTRY POINT	
12/4	7.8			·		been met for this day?	EP-A	
12/5	フラ					Lins day:		
12/6	7.6						PWS ID 4191707	
12/7	7.5					PL	EASANT VALLEY ELEM SD #55	
12/8	7.4							
12/11	74		<u> </u>			Sample period: <u>Olcomber 2023</u> Month/Year		
12/12	74				ļ			
12/14	7.4	<u> </u>					-	
17/15	7.4	<u> </u>			ļ			
		<u> </u>	<u> </u>		ļ	Number of	excursions during this month:	
		ļ	 		ļ		eursions in 6 months is a violation. Entry	
	<u> </u>	ļ	 		ļ	Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.		
			ļ	<u>-</u>	ļ			
		<u> </u>	<u> </u>		 			
			<u> </u>			State.		
		<u> </u>			 	Reference emailed 1-10-2024		
		 	<u> </u>	 			erence C Willes	
	<u> </u>		<u> </u>		-		Minimum Water Quality	
		 	<u> </u>			-	Minimum Water Quality Parameter(s) as set by State:	
	<u> </u>	<u> </u>	_			-		
		<u> </u>	<u> </u>		-	1	pH 7.2	
	<u> </u>		 		 	-		
		 	 	-	╀			
		 	 		<u> </u>			
	<u> </u>	<u> </u>	-	ļ	├ ──			
	<u> </u>			<u> </u>	-	<u> </u>		
		 	 			Print Nan	ne: Loni Weinman	
	<u> </u>	-	 	-	 	Signature: Am M		
	<u> </u>	-	 		1	-1	10-2024	
<u> </u>	<u> </u>	<u> </u>	<u> </u>			<u> </u>		
No =	N = Ex	CUISIO	n) Tot a	ai N's	Ш2	Send to D	WP within 10 days after end of period	

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp