

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	7.3				
3	7.3				
4					
5					
6	7.3				
7	1.3				
8	7.7				
9	1.3 1.3 1.7 1.3				
10					
11					
12	7.2				
13	7.3				
14	7.2				
15	1.2				
16	1.3 7.2 1.3 1.3				
17					
18					
19	1.3				
20	1.3 1.2 1.3 1.3				
21	7.2				
22 23	1.2				
23	7.3				
24					
25					
26	7.4				
27	7.8				
28	1.2				
29	7.2				
30	7.8				
31					
o = N	= Exc	ursion)	Total	N's	

< <have< th=""><th>County: Li</th><th>nn A</th><th>gency: LINN COUNTY</th></have<>	County: Li	nn A	gency: LINN COUNTY		
minimums been met for	ENTRY POINT				
this day?	EP-A				
	PWS I	D 419	1712		
SEV	'EN OAK	MIDDI	LE SCHOOL		
Sample pe	riod:	Sept.	2022		
		Mont	h/Year		

Number of excursions during this month: ____

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

	num Wate neter(s) as	r Quality s set by Stat
рН	7.2	

Print Name: Paula Should crs
Signature: Paula Should crs
Date & Phone#: 9:30:22 541451.8456

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

dwp. dmce@dhsoha state or us