

Water Quality Parameter Monitoring Form
Lead & Copper Rule Corrosion Control

Day	pH	Temp	Chlor	Other	Y/N
1	8.1	58	1	/	y
2					
3					
4					
5	8	59	.6	/	y
6					
7	8	59	.8	/	y
8					
9					
10					
11					
12					
13	8	59	.8	/	y
14					
15	7.9	58	.9	/	y
16					
17					
18					
19					
20	8	57	.8	/	y
21					
22	7.9	58	.8	/	y
23					
24					
25					
26					
27	8	58	.8	/	y
28					
29	8.1	58	.9	/	y
30					
31					

<<Have
minimums
been met for
this day?

County: Lincoln Agency: LINCOLN COUNTY

ENTRY POINT

EP-B

PWS ID 4192040

EDDYVILLE CHARTER SCHOOL

Sample period: July/28

Month/Year

Number of excursions during this month: _____

(Over 9 excursions in 6 months is a violation.
Entry Point and Distribution excursions are
cumulative). An 'excursion' is any day in which the
water quality parameter(s) fall below the minimum
set by the State.

Reference

**Minimum Water Quality
Parameter(s) as set by State:**

pH 7.2

Print Name: Danny Wheeler

Signature: _____

Date & Phone#: 8/7/25

Send to DWP within 10 days after end of
sampling period

() = N = Excursion) **Total N's** 0

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: <http://healthoregon.org/dwp/>