

Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

ID #	Sample Location	pH	TEMP	Chlor	Other	Y/N
4/1	work Room	7.3	54	.4		Y
4/3	'	7.3	54	.3		Y
4/9	'	7.4	55	.4		Y
4/11	'	7.4	54	.4		Y
4/15	'	7.3	54	.5		Y
4/17	'	7.3	53	.4		Y
4/23	'	7.4	54	.3		Y
4/25	'	7.3	54	.3		Y
4/29	'	7.6	53	.3		Y

Has sample met the minimum(s)?
 County: Lincoln Agency: LINCOLN C
DISTRIBUTION
PWS ID 4192040
EDDYVILLE CHARTER SCHOOL
 Sample Period: 4/24
 Month/Year
 Sample Frequency: Every 6 months
 Distribution Samples required: 1

Number of excursions during this Sample Period = 0
 (Number of locations when any WQP was less than the minimum.)

Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.

Reference _____
Minimum Water Quality Parameters as set by State:
 pH 7.2

(N = No = Excursion) Total N's

Print Name: Danny Wreeder
 Signature: [Signature]
 Date: 5/3/24

Send to Drinking Water Program within 10 days after end of sampling period:
 OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350
 Phone (971) 673-0405 Website: <http://healthoregon.org/dwp/>