

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

-	ID#	Sample Location	рН	18.4	CHO	Other	Y/N	County: Lincoln Agency: LINCOLN C
$\mathbb{N}$		WR	1.8	55	.5	1	V	met the
	5	U	8	54	.3	1	1	minimum(s)?
ĺ	7	(1	(2)	22	1, 2	1	4	DWC ID 4100040
(	13	l r	8.7	27	1.4		/y	PWS ID 4192040
	15	11	8	56	.4	/	4	EDDYVILLE CHARTER SCHOOL
١	20	) ((	8	56	1,4		Á	May
	20	) \((	4.1	SC	1,5		ý	Sample Period:
	26	11	81	22	15		У	Month/Year
\	26	( \	8	54	14	1	4	Sample Frequency: Every 6 months
				- (			/	Distribution Samples required: 1
								Number of excursions during this
-								Sample Period =
-					۹.,		7.	(Number of locations when any WQP
22					N.			was less than the minimum.)
1	-					Age .		Note: Entry Point and Distribution
-						,49		Excursions are cumulative. Add Entry
-					=			Point and Distribution Excursions to get total for sample period.
-			v	E				
-	$\dashv$				)			Reference
-	_							Minimum Water Quality
-	_							Parameters as set by State:
-								pH 7.2
-								pri 7.2
-	-		N <sub>X</sub>					
-	_							_ 1
	_							a late
		(N = No = Excl	ursior	1) T	otal	N's 「	0	Print Name: Dudy will
						£.,		Signature:
		Sand to Drinking M	/ m.k. n. u.	D		***		Date: <u>66/35</u>

Send to Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/