

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

ID#	Sample Location	рН	18,4E	CHO	Other	Y/N	Has sample County: Lincoln Agency: LINCOLN C
4	word Rm	8	56		/	/	met the
6	(\	8	SS	ì		1	minimum(s)?
19	((8	55.5	1		4	DIVE ID 4102040
14	C)	8	35		/	V	PWS ID 4192040
18	((8	56	.8	/	1	EDDYVILLE CHARTER SCHOOL
20	(1	7.9	26	,9		1	1
26	()	8	26			Y	Sample Period: 109 28
28	((8	56			4	Month/Year
				101			Sample Frequency: Every 6 months
							Distribution Samples required: 1
							Number of excursions during this
							Sample Period =
							(Number of locations when any WQP
				A			was less than the minimum.)
							Note: Entry Point and Distribution
					=	,	Excursions are cumulative. Add Entry
							Point and Distribution Excursions to get total for sample period.
						}	•
							Reference
							Minimum Materia
							Minimum Water Quality Parameters as set by State:
							pH 7.2
							1
(N = No = Excursion) Total N's Print Nam							Print Name: Lany Lucle
Signat							Signature:

Send to Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/