

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

D#	Sample Location	рН	18.40	CHO	Other	Y/N	< Has sample County: Lincoln Agency: LINCOLN C
1	HeathRim	7.6	68	1	/	1	met the DISTRIBUTION
3	U	7,6	67		/	1/	minimum(s)?
9	()	7.6	67		/	y	PWS 1D 4102040
	(,	7.7	68		/	У	PWS ID 4192040
5	((7.7	68		/	Y	EDDYVILLE CHARTER SCHOOL
7	S (7,6	67		1	ý	
93 95	\	7.6	68 68		/	y	Sample Period: Sept 25
		7,6	00	1	/	У	Sample Frequency: Every 6 months
							Distribution Samples required: 1
							Number of excursions during this Sample Period =
							(Number of locations when any WQP was less than the minimum.)
					1		Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.
							Reference
							Minimum Water Quality Parameters as set by State:
							pH 7.2
						- 1	
	(N = No = Excursion) Total N's				N's		Print Name: Comy while
(Signature:	
	Sand to Drinking Water Day						Date: 100/25
	Send to Drinking Water Program within 10 days after end of sampling period:						
	OHA Drinking Wa	ater F	Progra	am, F	90 B	ox 14	4350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: http://healthoregon.org/dwp/