

## Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	рН	Alk	COND	TEMP	Y/N	<>Have County: Columbia Agency: COLUMBIA COUNTY
1						minimums ENTRY POINT
2						been met for this day?  EP-A
3						this day:
4						PWS ID 4193427
5				· · · · ·		DYNO NOBEL INC
6						$\mathcal{A}$ ,
7	8.01	104.5	256.7	14.2	<b>Y</b>	Sample period: <u>Junary 2023</u> Month Year
8						Month'A ear
9						
10						Number of excursions during this month: $\underline{arphi}$
11			<u>.</u>			. (Over 9 excursions in 6 months is a violation.
12	1.95	93.5	259.6	13.4	Υ	Entry Point and Distribution excursions are
13						cumulative). An 'excursion' is any day in which the
14						water quality parameter(s) fall below the minimum
15						set by the State.
16						
17						Reference
18						
19	8.05	91.5	J.M.0	16.9	Y	Minimum Water Quality
20						Parameter(s) as set by State:
21						pH 7.2
22						- Bacarrate to contemporare -
23						
24					L	
25						
26						
27	1.90	95.0	2568	13.9	Y	Print Name: Heather Ebert Signature: Diath Severt
28						Signature: Olathor Severt
29						Date & Phone#: March 6,2023 503-366-8919
30			<u> </u>			Send to DWP within 10 days after end of
31				<u> </u>		sampling period
No = N = Excursion) Total N's						

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/