

Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	pH	Alk	COND	TEMF	YIN	
1						
2	7.76	75.1	227,8	13.6	7	
3						
4						
5						
6						
7						
8						
9	7.68	71.6	223.9	13.9	Y	
10						
11						
12						
13						
14						
15						
16	7.81	80.3	233.3	13.5	Y	
17						
18						
19						
20						
21						
22						
23	8.08	88.2	257.0	14.2	Y	
24						
25						
26						
27						
28						
29						
30	7.15	85.0	259.8	14.2	Y	
31						
10 = N	o = N = Excursion) Total N's 💋					

<<Have
minimums
been met for
this day?</pre>

County: Columbia Agency: COLUMBIA COUNTY

ENTRY POINT

EP-A

PWS ID 4193427 DYNO NOBEL INC

Sample period: <u>December</u> 2024

Month/Year

Number of excursions during this month: 💋

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference

Minimum Water Quality
Parameter(s) as set by State:

pH 7.2

Print Name: St	phenie	Andrews
Signature: 🎿	turi	an
Date & Phone#	1/6/2	5 503-366-8920

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/