

Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	рН	Alk	COND	TĖME	YIN
1		and construction	The state of the state of		
3					
4					
5					
6	7.88	84.8	251.0	13.9	4
7		·			
8					
9					
10					
11					
12					
13	7.85	81.1	258.7	13.1	Y
14					
15					
16					
17					
18					
19					
20					
21	7.82	86.2	255.9	12.8	1
22					
23					
24					
25					
26					
27	7.85	88.6	249.1	12.1	Y
28					
29					
30					
31					
lo = N	J = Ехс	ursion) Total	N's	0

<<Have
minimums
been met for
this day?</pre>

County: Columbia Agency: COLUMBIA COUNTY

ENTRY POINT

EP-A

PWS ID 4193427 DYNO NOBEL INC

Sample period: Jumy 2025

Month/Year

Number of excursions during this month: ______

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference

Minimum Water Quality
Parameter(s) as set by State:

pH 7.2

Print Name: Stephenic Andrews
Signature: 4 / / / / / / / S 603-366-8920
Date & Phone#: 2/4/25 603-366-8920

Send to DWP within 10 days after end of sampling period.

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/