

## Water Quality Parameter Monitoring Form

## Water Quality Parameter Montes.....

υay	рН	Alk	Phos	Other	Y/N	< <have< th=""></have<>
1,		Control Control Control				Have minimums been met for this day? PWS ID: 41 PWS ID: 41 PWS ID: 41
2						been met for this day? PWS ID: 41 9 3 7 1 1
3	•					
4						
5	7.2		1.40		y	Entry Point: A - Boiler Room
6					1	Sample Period: 8/25
7					les I	Month/Year
8	7.2		1.46		Y	Number of excursions* during this month:
9					- 1	(Count the number of days when any WQP was
10						less than the minimum required)
11	7:1		1.60		7	
12		300.3				Total excursions during the previous 5 months:
13	- 0		1			(Over 9 excursions in 6 months is a violation. Entry
14	7.2		1.58		Y	Point and Distribution excursions are cumulative)
15						For OHA use only
16						
17	- (		5 4 5			Minimum Water Quality
18 19	7.5		1.65		Y	Parameters as set by
20						pH 7.0
21						Alk (Alkalinity)
22	7 7		101	Bay 183	1	PO4 1.0 (Orthophosphate)
23	1, [		1.56		7	Other ( )
24						
25	7.8		1.55			
26	110		1.93		7	
27						1 64 4
28						Print Name:
29	8.0		1,54		Y	Signature:
30	210		110		1	Date: 9.2.25
31						Send to DWP within 10 days after end of
- ^	= Eva	walas	Tota	LNU. F	2	sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/