

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1					
2					
3					
4					
5	7.4	95			N
6					
7					
8					
9					
10	7.3	37			N
11					
12					
13					
14					
15					
16					
17	7.26	40			N
18					
19		1			
20				The second secon	
21			-		
22					
23					
24	7,4	34			2
25					
26			-		
27					
28	7.8	36			7
29					+
30					
31					
10 = 1	o = N = Excursion) Total N's				0

County: Marion Agency: MARION COUNTY MINIMUMS been met for this day?
EP-A
PWS ID 4193768
ABIQUA SCHOOL

Sample period: OCA 7022

Month/Year

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference
Minimum Water Quality Parameter(s) as set by State:
pH 7.2 Alk 30.0 (Alkalinity)
Print Name: Share Sancano (Signature: Men Muse Sancano) Date & Phone#:

Send to DWP within 10 days after end of

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

sampling period