

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1					
2					
2 3 4					-
	5.3	58			N
5					
6					
7					
8					
9					
10					
11	8.2	32			7
12					
13					
14					
15					
16					
17					
18	8.0	41			N
19					
20					
21					
22					
23					
24					
25	81	43			N
26					
27					
28					
29					
30					
31					
10 =	N = Ex	cursion	n) Tota	al N's	6

< <h< th=""><th>ave</th><th></th><th></th></h<>	ave		
mini	mui	ms	
beei	n m	et f	or
this	day	?	

County: Marion	Agency: MARION COUNTY	
ENTRY	POINT	
EP.	-A	
PWS ID 41	193768	
ABIQUA S	CHOOL	

Sample	period:	APR 23
-		Month/Year

Number of excursions during this month: _________

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference
Minimum Water Quality Parameter(s) as set by State:
Alk 30.0 (Alkalinity)

Print Name: 5 War SAUCADO
Signature: Musho
Date & Phone#: 25 Apr 1223
Send to DWP within 10 days after end of
sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/