

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N	<>Have County: Marion Agency: MARION COUNTY
1						Mad the tree tree o
2						been met for ENTRY POINT
3	7.9	67	盛			this day?
4						PWS ID 4193768
5						ABIQUA SCHOOL
6						
7						Sample period: Accid
8						Sample period: April 7823 Month/Year
9						
10						Number of excursions during this month:
12						(Over 9 excursions in 6 months is a violation.
13						Entry Point and Distribution excursions are
14						cumulative). An 'excursion' is any day in which the
15						water quality parameter(s) fall below the minimum set by the State.
16	7.9	1.1				
17						
18						Reference
19						Minimum Weter Orrellt.
20						Minimum Water Quality Parameter(s) as set by State:
21						production and control processing and control
22						pH 7.2
23						Alk 30.0 (Alkalinity)
24						
25						
26						
27						Print Name: Sixon Sondal
28	7	£)				Signature:
29 30	0.1	58				Date & Phone#: 79 ACC 24
31						Send to DWP within 10 days after end of
			\			sampling period
10 - N	ı — ⊏XC	ursion) Tota	I N'S	0	

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/