

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N	< <have< th=""><th>County: Marion Agency: MARION COUNTY</th></have<>	County: Marion Agency: MARION COUNTY
1						minimums	
2						been met for	ENTRY POINT
3	8.6	45				this day?	EP-A
4							PWS ID 4193768
5							ABIQUA SCHOOL
6						•	
7							
8						Sample per	riod: September 7025 Month/Year
9		,					Wionally real
10	777	38				Number of exc	cursions during this month:
11							ions in 6 months is a violation.
12						Entry Point and	Distribution excursions are
13 14						cumulative). A	n 'excursion' is any day in which the
15						water quality pa set by the State	arameter(s) fall below the minimum
16						Set by the State	₹.
17	8.0	111					•
18	D.0	71				Referen	ce
19					_		
20							inimum Water Quality
21		-				Fe	rameter(s) as set by State:
22						į į	oH 7.2
23							Alk 30.0 (Alkalinity)
24	9.0	36					
25						Ĭ.	
26						5	
27						Down A All	
28							ne: Share Sanciao
29	9.0	33				Signature	Stur & W
30							none#: 29 Sept 25
31						Send to D	WP within 10 days after end of
o = N = Excursion) Total N's					ϕ	sampling _l	period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/