Health Authority

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N	< <hav< th=""><th> e</th><th>County: Clackamas Agency: CLACKAMAS COUNTY</th></hav<>	 e	County: Clackamas Agency: CLACKAMAS COUNTY	
1				,		minimu		ENTRY POINT	
2						been n			
3						this da	y?	EP-A	
4								PWS ID 4194670	
5					v	OREGON TRAIL SD - BORING MID SCH			
6									
7						Sample period: October '04			
8								Month/Year	
9								- M	
10						Numl	per of e	xcursions during this month:	
11						(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.			
12									
13									
14	7.3			15°C					
15						set by	rine Sia	ue.	
16	.						*		
17							-Refere	ence	
18									
19								Minimum Water Quality	
20						*	F	Parameter(s) as set by State:	
21								pH 7:2	
22									
23						1			
24						81			
25						2		T.	
26									
27							Print Na	me: Chelsea Lincoln Lane)	
28	7:3			150			Signatu	7	
29								Phone#: 11/7/24	
30								DWP within 10 days after end of	
31							sampling		
N = N	= Excu	ırsion)	Total	N's	20				

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/