## Health Authority

## Water Quality Parameter Monitoring Form

## Lead & Copper Rule Corrosion Control

	Day	pН	Alk	Phos	Other	Y/N	< <hav< th=""><th>/e</th><th>County: Clackamas Agency: CLACKAMAS COUNTY</th></hav<>	/e	County: Clackamas Agency: CLACKAMAS COUNTY	
. ]	1						minim		ENTRY POINT	
	2							net for		
Ī	3	7.4	120		17°C	V	this da	ıy?	EP-A	
	4					1		*	PWS ID 4194670	
	5						OREGON TRAIL SD - BORING MID SCH			
	6						Sample period: February 2025  Month/Year			
	7									
	8									
	9						~.			
_	10						Number of excursions during this month:   (Over 9 excursions in 6 months is a violation.  Entry Point and Distribution excursions are			
<u>_</u>	11									
-	12	·								
-	13						cumulative). An 'excursion' is any day in which the			
- I-	14						water quality parameter(s) fall below the minimum set by the State.			
1	15						Set D	y III <del>e</del> Sia	ie.	
-	16							•		
-		7.4	120		1700	1/		_Refere	nce	
_	18					1.				
	19								Inimum Water Quality Parameter(s) as set by State:	
<u>-</u>	20						•	F	arameter(s) as set by State.	
-	21								pH 7:2	
-	22			+						
-	23   24					$\dashv$				
-	25								· P	
-	26				-+	-		- •		
-	27								16/1	
-	28					_	Print Name: Chelsea Lincoln Lane			
12	29		-+		,			Signatur	hone#: 3/3/25 (6/8-10442	
1	304				T I					
15	31								OWP within 10 days after end of	
(No	(No = N = Excursion) <b>Total N's</b>									

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/